

WELD-AID PRODUCTS – YORK PRODUCTS DIV.

MATERIAL SAFETY (313) 883-6977 14650 DEQUINDRE
DATA SHEET (313) 883-4930 fax DETROIT, MI 48212

Issue Date: 03-18-1993 rev. 10-31-09
Trade Name and Synonyms: YORK'S NOZZLE GEL SPAT-R-PRUF COMPOUND 101
Product Code: YRK101

SECTION 2 HAZARDOUS INGREDIENTS

Does product contain hazardous ingredients? NO
Does product contain carcinogens? (NTP, IARC, OSHA) NO

SECTION 3 CHEMICAL DATA

Boiling Point IBP: 212 DEGREES F Specific Gravity (WATER=1): >1.0
Vapor Pressure(MMHG): 18 Melting Point: N/A
Vapor Density(AIR=1): >1
Solubility in Water: COMPLETE
Appearance and Odor Information: GOLD COLOR, EXTREMELY VISCOUS, MILD ODOR

SECTION 4 FIRE AND EXPLOSION HAZARD DATA

Flash Point: NONE Flammable Limits-LEL= N/A UEL= N/A
Extinguishing Media: WATER
Special Fire Fighting Procedures: NONE

SECTION 5 HEALTH HAZARD DATA

Health Effects: EYES AND SKIN-MAY CAUSE IRRITATION. INGESTION - MAY IRRITATE
GASTROINTESTINAL TRACT.
Primary routes of entry: SKIN AND INGESTION
Medical conditions aggravated by exposure: UNKNOWN
Emergency first aid procedures:
QUICKLY FOLLOW DIRECTIONS BELOW, CONTACT PHYSICIAN OR POISON CONTROL
CENTER. GET QUICK MEDICAL ATTENTION IF ANY ILL EFFECTS CONTINUE OR DEVELOP
LATER.
EYES-FLUSH EYES WITH PLENTY OF WATER WHILE REMOVING ANY CONTACT LENSES,
THEN HOLD EYELIDS OPEN AND CONTINUE FLUSHING FOR 15 MINUTES.
SKIN-REMOVE ANY CONTAMINATED CLOTHING, THEN WASH AFFECTED SKIN WITH SOAP
AND WATER. INGESTION-IF SWALLOWED, CONSULT A PHYSICIAN.

SECTION 6 REACTIVITY DATA

Is product stable? YES
Conditions to avoid/stability: AVOID HEATING TO ABNORMAL TEMPERATURES
Incompatibility (Materials to Avoid): AVOID CONTACT WITH STRONG OXIDANTS.
Hazardous Decomposition Products: OXIDES OF CARBON MAY BE FORMED UPON COMBUSTION
Will hazardous polymerization occur? NO
Conditions to avoid/stability: NONE

SECTION 7 SPILL, LEAK AND DISPOSAL PROCEDURES

Steps to be taken in case material is released or spilled: WIPE OR MOP UP SPILLS, THEN RINSE WITH WATER. FLOORS MAY BE SLIPPERY, USE CAUTION TO AVOID FALLS.

Waste Disposal Method: TRIPLE RINSE CONTAINER, THEN DISCARD IN TRASH.

SECTION 8 SPECIAL PROTECTION INFORMATION

Respiratory Protection: NONE REQUIRED

Protective Clothing: NONE REQUIRED

Eye Protection: SAFETY GLASSES REQUIRED

Work Practices: ALWAYS FOLLOW SAFE WORK PRACTICES

SECTION 9 SPECIAL PRECAUTIONS AND ADDITIONAL INFORMATION

Precautions to be taken in handling and storage: CAUTION. KEEP OUT OF REACH OF CHILDREN. STORE IN A COOL DRY AREA. DO NOT ALLOW TO FREEZE. HOWEVER, IF PRODUCT DOES FREEZE, ALLOW TO THAW, FREEZING WILL NOT EFFECT PERFORMANCE

Other Precautions: AVOID CONTACT TO EYES AND SKIN

Other Comments: NONE

These sheets were compiled from the latest available information and reliable sources. Procedures are based on accepted usage. They are not necessarily all-inclusive and may vary in every circumstance. York Sales Company provides no warranties either expressed or implied and assumes no responsibility for the accuracy or completeness of the data herein.

HAZARDOUS MATERIAL IDENTIFICATION SYSTEM

RATING

HEALTH 0

FIRE 0

REACTIVITY 0

KEY:0-MIN 1-SLIGHT 2-MOD 3-SERIOUS 4-SEVERE